#### DEPARTMENT OF TRANSPORTATION

DIVISION OF ENGINEERING SERVICES Office of Structural Materials

Quality Assurance and Source Inspection

Bay Area Branch 690 Walnut Ave.St. 150 Vallejo, CA 94592-1133 (707) 649-5453 (707) 649-5493



Contract #: 04-0120F4

Cty: SF/ALA Rte: 80 PM: 13.2/13.9

File #: 69.28

### WELDING INSPECTION REPORT

Resident Engineer: Pursell, Gary **Report No:** WIR-012495

Address: 333 Burma Road **Date Inspected:** 06-Mar-2010

City: Oakland, CA 94607

**OSM Arrival Time:** 700 **Project Name:** SAS Superstructure **OSM Departure Time:** 1900 **Prime Contractor:** American Bridge/Fluor Enterprises, a JV

Contractor: Zhenhua Port Machinery Company, Ltd (ZPMC), Changxing Island **Location:** Shanghai, China

**CWI Name: CWI Present:** Yes No Gong Wai **Inspected CWI report:** Yes N/A **Rod Oven in Use:** Yes No No N/A N/A **Electrode to specification:** Yes No Weld Procedures Followed: Yes No N/A N/A **Qualified Welders:** Yes No **Verified Joint Fit-up:** Yes No N/A N/A Yes N/A **Approved Drawings:** Yes No **Approved WPS:** No Yes No N/A **Delayed / Cancelled:** 

34-0006 **Bridge No: Component:** OBG COMPONENT

### **Summary of Items Observed:**

On this date Caltrans OSM Quality Assurance (QA) Inspector, Subhasis Bera was present during the times noted above for observations relative to the work being performed.

In process Inspection

Bay #14

This QA Inspector observed the following work in progress:

FCAW in the 1G position for the OBG Segment 12CW, weld No.CA3011-003. The welder is identified as #045175. ZPMC QC is identified as Mr. Li Ming Yang. The welding variables recorded by QC appear to comply with WPS-B-T-2231-Tc-U4b-F.

SMAW in the 4G position for the OBG Segment 11DW, weld No.SEG071C-001. The welder is identified as #047864. ZPMC QC is identified as Mr. Liu Hua Jie. The welding variables recorded by QC appear to comply with WPS-B-P-2214-Tc-U4b-FCM-1.

SMAW in the 4G position for the OBG Segment 11DW, weld No.SEG071A-015. The welder is identified as #037723. ZPMC QC is identified as Mr. Liu Hua Jie. The welding variables recorded by QC appear to comply with WPS-B-P-2214-Tc-U4b-FCM-1.

FCAW in the 2F position for the OBG Segment 12AW, weld No.CA-3006C-029/030. The welder is identified as #202122. ZPMC QC is identified as Mr. Liu Hua Jie. The welding variables recorded by QC appear to comply

# WELDING INSPECTION REPORT

(Continued Page 2 of 3)

with WPS-B-T-2132.

FCAW in the 3G position for the OBG Segment 11DE, weld No.SSD16A-PP104-001. The welder is identified as #044824. ZPMC QC is identified as Mr. Zhong Guo Hui. The welding variables recorded by QC appear to comply with WPS-B-T-2233-B-U2-F.

Ultrasonic Testing (UT)

This QA Inspector performed Ultrasonic testing (UT) 10% of the area previously tested and accepted by ZPMC Quality control personnel. This QA inspector generated a (UT) report for this date. The members are identified as OBG Segment 9AW, 9CW and 9DW.

The Weld Designations are as follows

CA055-017,018 CA062-069,070 CA065-033,034

Unless otherwise noted, all work observed on this date appeared to generally comply with applicable contract documents.







# WELDING INSPECTION REPORT

(Continued Page 3 of 3)

## **Summary of Conversations:**

No relevant conversations

#### **Comments**

This report is for the purpose of determining conformance with the contract documents and is not for the purpose of making repair or fit for purpose recommendations. Should you require recommendations concerning repairs or remedial efforts please contact Eric Tsang 150-0042-2372, who represents the Office of Structural Materials for your project.

Inspected By:	Bera,Subhasis	Quality Assurance Inspector
Reviewed By:	Patterson,Rodney	QA Reviewer